

2 MACHINE CONSTRUCTION

2-3 Axis Definition

This section describes the definition of the coordinate system and axes.

(1) Axis definition

X₁, X₂, X₃-axis:

Right angle direction of spindle center line

Z₁, Z₂, Z₃-axis:

Longitudinal direction of turret motion

B₂-axis (option):

Longitudinal direction of the sub spindle

C-axis (option):

Rotational direction of spindle

Y₁, Y₂-axis (option):

Vertical direction of X₁-Z₁ plane

NOTE: Motion direction is defined by viewing the machine from its front. See Fig. 2-3.





Fig. 2-3 Axis Definition